



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

March 07, 2013

Reviewed: 

Mine Name: Perpetual Storage Vault	Permit Number: M/035/0013
Operator Name: Perpetual Storage Inc.	Inspection Date: September 30, 2009
Inspector(s): L Hepler	Time: 9:00 AM
Other Participants: Operator Representative	Mine Status: Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Bond Renewal Date: No bond on file, so no renewal date. **Bond Amount:** \$0 **Permit fee** has not yet been paid/recorded for 2013

Purpose of Inspection: Routine annual Inspection. This site was last inspected as a small mine 12/22/2005, by Paul Baker.

Inspection Summary: There is a current May 11, 1992 NOI on file with the Division. The 12/22/2005 inspection by Paul Baker is an excellent summary of the small mine permit. At the time of this inspection, the condition of the site was as written in the 12/22/2005 inspection report. In summary, the site is a commercial operation, which satisfies the State of Utah R-647, as a post mining land use. Photos were taken to document site conditions.

Conclusions and Recommendations: Operator had verbally requested that the smo be closed on 12/22/2005. If the Operator still wants to retire the permit, he should reclaim the old access road and plug the horizontal drill hole; then submit form MR-SITE to OGM. If the Operator wants to keep the permit open, a one acre bond should be submitted to OGM. Permit fees are due. OGM to continue annual inspections and monitor the site when in the area.

Inspector's Signature



LAH:pb

cc: Earl Dean Willden

O:\M035-SaltLake\S0350013-Perpetualstorage\inspection\Insp-09302009.doc





PVC Collar of Horizontal Drill hole



Entrance to Storage facility



Slope below site



Drainage from parking lot